## Public Record – Summary Information On Motor Fuel Underground Storage Tanks (USTs)

## **General Information**

Public Record Posted Date: 10/15/07

Total Number Of UST Facilities: 1,554
Total Number Of USTs: 3,199

## **Summary Information For On-Site Inspections**

Number Of UST Facilities Inspected: 357

Inspection Period Dates: 9/1/06 To: 9/1/07

Percent Compliance (Combined Measure): 54%

Note: Tank, facility, and on-site inspection information is based on inspections of UST motor fuel facilities only; heating oil USTs are not included. On-site inspections measure compliance with State of Maine and U.S. EPA regulations and laws governing the prevention and detection of petroleum releases or discharges.

## **Summary Information For Releases**

Number Of Confirmed UST Releases: 86
Release Reporting Period Dates: 9/1/06 To: 9/1/07

Summary Information For Release Sources And Causes (does not include bare steel tanks and piping)

| (uodo not merculo baro etect tamte una piping) |                    |     |                     |     |           |     |                    |     |       |     |         |   |   |     |
|--|--------------------|-----|---------------------|-----|-----------|-----|--------------------|-----|-------|-----|---------|---|---|-----|
|  |                    |     | Cause               |     |           |     |                    |     |       |     |         |   |   |     |
| Soul   | Spill/<br>Overfill |     | Phys/Mech<br>Damage |     | Corrosion |     | Install<br>Problem |     | Other |     | Unknown |   |   |     |
|  | #                  | %   | #                   | %   | #         | %   | #                  | %   | #     | %   | #       | % | # | %   |
| Tank   | 9                  | 23  |                     |     | 4         | 17  | 1                  | 25  | 1     | 100 |         |   | 3 | 43  |
| Piping   | 8                  | 20  |                     |     | 5         | 22  | 1                  | 25  |       |     |         |   | 3 | 43  |
| Dispenser                                      | 13                 | 32  | 1                   | 10  | 14        | 61  | 2                  | 50  |       |     |         |   |   |     |
| Delivery<br>Problem                            | 9                  | 23  | 9                   | 90  |           |     |                    |     |       |     |         |   |   |     |
| Unknown  | 1                  | 2   |                     |     |           |     |                    |     |       |     |         |   | 1 | 14  |
|  |                    |     |                     |     |           |     |                    |     |       |     |         |   |   |     |
| Totals   | 40                 | 100 | 10                  | 100 | 23        | 100 | 4                  | 100 | 1     | 100 |         |   | 7 | 100 |

# = number, % = percent of column total number

Note: Release, source and cause information is based on reported releases at motor fuel UST facilities constructed of approved corrosion resistant materials (no bare steel). Source and cause data were compiled from data collected in the course of investigating UST system releases and using EPA's LUST Site Release Reports.

For information about specific petroleum spills and releases in your town go to the Department's <u>Hazardous and Oil Spill System (HOSS) online report service</u>. For questions about the information on this page, please contact George Seel at (207) 287-2651 or <u>george.j.seel@maine.gov</u>.